

Imray Correction Notice

29 March 2010

Chart B311 WGS 84

Edition Jul 2009

Date of printing Jul 2009

The following corrections should be noted:

1 Tobago Cays, Mayreau

Mariners are advised that the pillar Lt buoy Fl.R.4s to the west of Grand Col Pt (12°38'26N 61°24'09W) is often missing.

If this is the case, then the Range 15 transit should be used to clear the dangerous rock. (ILNW 84/10)